



## **MIYOTA**





## Battery consumption could be minimum by pulling out the stem





<Battery Detector Function> As warning second hand steps every 2 seconds When battery becomes nearly empty. (except for Cal. 9T22/15&9U15)


## Time measurement

## **Accuracy**


**Package** 


The unit (gate) time of measurement must be set at "10 sec." and the measurement must be performed in the form of complete watch.






**MIYOTA** 





Plating



(01)	<u>^</u>			Quantity		Cal. No. :
)	<u></u>			Unit	1/1000 mm	
	<u></u>			Scale	20:1	Parts:
065-495	<u>4</u>		Date		065-495	
				Drawn		065-495
0 6	<u>/2</u>			Checked	T. Hiruta	Name :
	<u>_1</u>			Approved		SETTING STEM
МЧ	Material SuS420F-DG				Drawing No. : 49508000	
$\perp$	Heat Treatmo	Heat Treatment 焼入焼戻		General Tolerances		
*	Hardnes	ss	H V 5 5 0	Dimensions		

Angles